



**NOTICE to MARINERS**

**NO: 1/2019**

**LERWICK HARBOUR – HOLMSGARTH MOORING DOLPHIN**

Mariners are advised that repair works are to commence this week to the Holmsgarth Mooring Dolphin.

Mooring Dolphin Position:  
**60° 09.80' N, 001° 09.30' W**

Operations will be conducted with personnel at the waterline and underneath the dolphin, and is expected to take approximately one month to complete.

Mariners are requested to observe extreme caution, minimise vessel wash by passing at slow speed and maintain a wide berth when transiting the area.

Mariners are advised that assisting craft used may not be displaying lights and shapes in accordance with the Merchant Shipping (Distress Signals and Prevention of Collision) Regulations 1996

Mariners due to transit the area are requested to contact Port Control and maintain a listening watch on VHF Marine Channel 12 & 16 at all times.

9 January 2019

Captain Alexander M. Simpson  
Harbourmaster